





Utility Conflict Report

OWNER	Utility	CPS	Corridor	BANDERA	SITE PHOTOS  
	Contact	BILL FEY	ID	4580	
GENERAL INFO	Utility	GAS			
	Size and Material	UNKNOWN			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	LONGITUDINAL			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	288			
	Station	1723+20			
	Offset	-20			
	Latitude	+29.485174			
	Longitude	-98.60613			
SUE	Level of Investigation Req'd	QLA			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	ACCOMMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY CONFLICT CREATED			
	Comment	811 - Underground gas and electric/cable lines. Request As-builts for line depth verification			
Date Collected 11/20/2018 10:43:52 AM Date Modified 11/21/2018 2:51:37 PM					

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio | Austin | Houston | Fort Worth | Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com