

Utility Conflict Report

	1							
IER	Utility	CHARTER		Corridor	SW MILITA	ιRY	SITE PHOTOS	
OWNER	Contact	FRANK CY	PRIAN	ID	1162			
GENERAL INFO	Utility		COMMUNICATIONS					
	Size and Material		OVERHEAD TELECOMM LINES					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE		
	Longitudinal or Crossing		LONGITUDINAL					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 2	212						
	Station 9	948+52.40						
	Offset -	17.91					35	
	Latitude +	Latitude +29.356856						
	Longitude .	-98.50142					3 1	
SUE	Level of Investigation Req'd		NONE				Way The State of t	
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED Related to utility ID 7033					
	Comment							
Date Collected				Date I	Modified	12/18/2	2018 4:05:31 PM	

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800