

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>	
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	3167		
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC				
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER				
	<b>Accessible Route</b>	ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	<b>Longitudinal or Crossing</b>	CROSSING				
	<b>Placement Relative to ROW</b>	INSIDE ROW				
<b>LOCATION</b>	<b>Sheet No.</b>	146				
	<b>Station</b>	612+72.73				
	<b>Offset</b>	16.8319				
	<b>Latitude</b>	+29.356532				
	<b>Longitude</b>	-98.53443				
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE				
	<b>Test Hole No</b>	N/A				
	<b>Test Hole Depth</b>	N/A				
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT				
	<b>Estimated Resolution Date</b>					
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED				
	<b>Comment</b>	Pole ID: LW 34774; 456004 Pole to front of sidewalk = 3'-11" Sidewalk width = 5'-0" Pole to guy wire 1 = 14'-9" Pole to guy wire 2 = 20'-8" CATV cable				
	<b>Date Collected</b>	7/31/2018 2:34:53 PM	<b>Date Modified</b>	11/28/2018 6:59:12 AM		

