

Utility Conflict Report

OWNER	Utility	CPS		Corridor ID	SW MILITAF	ARY	SITE PHOTOS	
	Contact	JAKE MAR	INEZ		4084			
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			UTE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	129						
	Station 5	529+85.51						
	Offset 2	27.943						
	Latitude -	+29.358117						
	Longitude	-98.56043					*	
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/14/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole ID: LW 43553; 446681 Pole to traffic signal box = 3'-2" CATV cable					
Date Collected 7/23/2018 7:51:07 AM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800