

Utility Conflict Report

ER	Utility	CPS		Corridor	SW MILITARY	SITE PHOTOS
OWNER	Contact	JAKE MAR	TINEZ	ID	4126	
	Utility		ELECTRIC			
INFO	Size and Material		STANDARD POWER POLE, TIMBER			
GENERAL	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		JTE	
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No. 1	41				
	Station 5	574+84.77				
	Offset 1	6.4704				
	Latitude +	-29.356958				
	Longitude .	-98.54635				
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			
	Test Hole Depth		N/A			
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date					
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Pole ID: 17135 Pole to back o Pole to front o Pole diameter Pole to ramp =	f curb = 3'-0" sidewalk = 3'-9" =14"		
	Date Collected 7/27/2018 11:24:11 AM Date Modified 11/28/2018 6:59:12 AM					

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800