

Utility Conflict Report

04							
当	Utility	SAWS		Corridor	SW MILITA	RY .	SITE PHOTOS
OWNER	Contact	ANN PECH	IE	ID	4150		
GENERAL INFO	Utility		WATER				
	Size and Material		STANDARD WATER VALVE, CAST IRO			RON	
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTI			JTE	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	155					
	Station 6	676+63.86					
	Offset						
	Latitude -						
	Longitude	-98.51435					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
ON	Resolution Status		NO RESOLUTION WAS REQUIRED				
RESOLUTIO	Comment		Valve to face of curb = 1'-1" Valve to back of curb = 2'-11 1/2" Sidewalk width = 4'-9 1/2" Top of valve to surface = 2'-2 1/2" Lid flange thickness = 2" Total lid thickness = 3"				
Date Collected 8/1/2018 11:48:15 AM Date Modified 11/28/2018 6:59:12 AM							018 6:59:12 AM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800