

Utility Conflict Report

IER	Utility	SAWS		Corridor	SW MILITA	SITE PHOTOS
OWNER	Contact	ANN PECH	E	ID	4193	
GENERAL INFO	Utility		WATER			
	Size and Material		STANDARD WATER VALVE, CAST IRON			RON
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No.	165				
	Station 7	715+45.83				
	Offset 1	15.57				
	Latitude -	titude +29.356667			-	
	Longitude -98.50230					
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			
	Test Hole Depth		N/A			+ 17
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date					
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Top of valve to surface = 3'-6" Lid flange thickness = 1 1/2" Total lid thickness = 2" Back of curb to valve = 3'-2" Valve to back of sidewalk = 2'-8 1/2" Sidewalk width = 6'-7"			
	Date Collected	8/6/2018 10:	:41:41 AM	Date I	Modified	12/18/2018 4:28:10 PM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800