

## **Utility Conflict Report**

						_	
IER	Utility	CPS		Corridor	SW MILITA	SITE PHOTO	
OWNER	Contact	JAKE MAR	TINEZ	ID	4223		
	Utility		ELECTRIC				
INFO	Size and Material		STANDARD POWER POLE, TIMBER				
GENERALI	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
OCATION	Sheet No.	68					
	Station 7	25+14.27					
	Offset	5.45					
	Latitude -	-29.356585					
_	Longitude	-98.49917					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
0,	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		11/21/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole ID: 383964 Back of curb to pole = 3'-4" Sidewalk width = 6'-2" Back of inlet to pole = 2'-6" Back of sidewalk to pole = 1'-9"				
	Date Collected         8/7/2018 9:37:46 AM         Date Modified         11/28/2018 Page 11/						018 6:59:12 AM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800