

Utility Conflict Report

ER	Utility	CPS	Corridor	BANDERA	SITE PHOTOS	
OWNER	Contact	BILL FEY	ID	4583		
0						
GENERAL INFO	Utility		GAS		NOSCTAN ATTOM	
	Size and Material		UNKNOWN			
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing		LONGITUDINAL			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No.	307				
	Station	1778+15				
	Offset	-40			NECTOR AND ADDRESS OF THE PROPERTY OF THE PROP	
	Latitude	+29.495314				
	Longitude -98.61894					
SUE	Level of Investigation Req'd		QLA			
	Test Hole No		N/A			
	Test Hole Depth		N/A			
RESOLUTION	Recommended Action		ACCOMODATE - RELOCATION			
	Estimated Resolution Date					
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			
	Comment		811 - underground gas line. Request As-			
			bulits for line depth verific	ilts for line depth verification		
	Date Collected		Date Modified 12/19/2018 11:48:30 AM			

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800