

Utility Conflict Report

IER	Utility	CPS		Corridor	SW MILITARY	SITE PHOTOS
OWNER	Contact	JAKE MAR	TINEZ ID	7047	The last A	
GENERAL INFO	Utility		ELECTRIC			FIBER OPTIC CATV CABLE
	Size and Material		STANDARD POWER POLE, TIMBER			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing		CROSSING			9
	Placement Relative to ROW		INSIDE ROW			3
LOCATION	Sheet No. 209					
	Station 9	Station 929+04.95				
	Offset -16.48					
	Latitude +29.356727					
	Longitude -98.50732					
SUE	Level of Investigation Req'd		NONE N/A N/A			
	Test Hole No					
	Test Hole Depth					
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date					
	Resolution Status		NO RESOLUTION WAS REQUIRED		REQUIRED	3/1
	Comment		Pole to back o Pole diameter Back of curb to	= 12"		

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

12/18/2018 4:01:22 PM

Date Modified

8/3/2018 9:47:24 AM

Date Collected