

Utility Conflict Report

IER	Utility	CPS		Corridor	SW MILITARY	SITE P
OWNER	Contact	JAKE MAR	TINEZ	ID	7055	
	Utility		ELECTRIC			
NFO	Size and Material		STANDARD POWER POLE, TIMBER			
GENERAL INFO	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			
EN	Longitudinal or Crossing		CROSSING			
0	Placement Relati	ve to ROW	INSIDE ROW			
_	Sheet No.	206				
9	Station	912+13.16				
Ä	Offset -	-16.35				
LOCATION	Latitude -	+29.356838				4
	Longitude	-98.51276				W 4 5
l	Level of Investigation Req'd		NONE			57250
SUE	Test Hole No		N/A			9 4
0,	Test Hole Depth		N/A			
	Recommended Action		NO CONFLIC	Т		
	Estimated Resolution Date					
N O	Resolution Status		NO RESOLUTION WAS REQUIRED			1
RESOLUTIO	Comment		Pole ID: 442504; LW57291 Back of curb to pole = 1'-10"			
S.						

SITE PHOTOS







Date Collected 8/3/2018 10:53:53 AM **Date Modified** 12/18/2018 4:01:27 PM