

## **Utility Conflict Report**

IER	Utility	CPS		Corridor	SW MILITARY	SITE PHOTOS	
OWNER	Contact	JAKE MAR	TINEZ	ID	7097		
0							
GENERAL INFO	Utility		ELECTRIC		1940011 4600091		
	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 195						
	Station 8	357+45.19					
	<b>Offset</b> -16.47						
	<b>Latitude</b> +29.356765						
	Longitude -98.52987					+	
SUE	Level of Investigation Req'd		NONE			umod	
	Test Hole No		N/A				
	Test Hole Depth		N/A			130	
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date					incred \$10.	
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole ID: 46229 Pole diameter Back of sidew Sidewalk width	= 10" alk to pole =			

8/3/2018 3:31:24 PM

**Date Collected** 

12/18/2018 4:01:59 PM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

**Date Modified**