

## **Utility Conflict Report**

OWNER	Utility	SAWS		Corridor	SW MILITA	RY.	SITE PHOTOS		
	Contact	ANN PECH					3		
O	Contact	ANNILON	_	טו	7104				
GENERAL INFO	Utility		WATER						
	Size and Material		STANDARD WATER VALVE, CAST IRON						
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	194							
	Station 8	352+87.73							
	Offset -	15.6418							
	Latitude -	+29.356778							
	Longitude	-98.53127							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Valve to curb ramp edge of concrete = 2'-2"			2'-2"			
			Top of valve to surface = 3'-6" Lid thickness = 2"						
	Date Collected 8/3/2018 4:08:55 PM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800