

Utility Conflict Report

IER	Utility	CPS		Corridor	SW MILITA	RY .	SITE PHO	OTO	
OWNER	Contact	JAKE MAR	TINEZ	ID	7107		P 1 5 5 2		
GENERAL INFO	Utility		ELECTRIC						
	Size and Material		STANDARD POWER POLE, TIMBER			¥. 950			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE	West Balls Ass.		
	Longitudinal or Crossing		CROSSING				8 2 5		
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 1	93						2	
	Station 8	337+88.92							
	Offset -	16.0686						M. Bak	
	Latitude +	-29.356801							
	Longitude -	-98.53604							
SUE	Level of Investigation Req'd		NONE					1	
	Test Hole No		N/A				A A		
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLIC	Т				A PAGE	
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Pole ID: 437825; LW34825 Conduit to back of sidewalk = 3'-9" min Pole diameter = 10" Back of curb to pole = 2'-5" Adjacent to existing VIA bus stop			n			
	Date Collected 8/6/2018 8:19:46 AM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800