

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	SW MILITARY	SITE PHOTOS		
	Contact ANN PECH		E		7133			
0								
GENERAL INFO	Utility		SANITARY SEWER					
	Size and Material		STANDARD MANHOLE, CAST IRON					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING			And the second		
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	179						
	Station	770+84.53						
	Offset -							
	Latitude -							
	Longitude	-98.55692						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE					
	Estimated Resolution Date							
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY					
	Comment		Bottom of cone to surface = 28"					
			Back of curb to manhole = 4'-3"					
	Date Collected 8/6/2018 11:17:47 AM Date Modified 12/17/2018 4:57:45 PM							

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800