

Utility Conflict Report

IER	Utility	CPS		Corridor	SW MILITARY	SITE P	
OWNER	Contact	JAKE MAR	TINEZ	ID	7134		
0							
0	Utility		ELECTRIC				
INF	Size and Material		STANDARD POWER POLE, TIMBER				
GENERAL INFO	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
Ä	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	179					
	Station	769+80.95					
	Offset	-16.19					
ŏ	Latitude	+29.358186					
二	Longitude	-98.55710					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommende	d Action	NO CONFLIC	T			
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED		REQUIRED	29	
	Comment		Pole ID: 4527 Pole to back of perpendicular Pole diameter Back of curb to	of driveway a to roadway = 12"	•	THAT TO CO	
	D-4- O-H4-1						

SITE PHOTOS





