



Utility Conflict Report

OWNER	Utility SAWS	Corridor RIGSBY	SITE PHOTOS		
	Contact NINA BITTLE	ID 219			
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD WATER VALVE, CAST IRON			
	Utility Conflict Description	WATER VALVE WITHIN PROPOSED SIDEWALK			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE			
LOCATION	Sheet No.	247			
	Station Origin				
	Start Station	156+74.13	End Station		
	Start Offset	10.68	End Offset		
	Latitude	29.39881912	Longitude		-98.425608825
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date				
	Resolution Status	UTILITY COORDINATION IN PROGRESS			
	Comment	ADJUST WATER VALVE LID TO PROPOSED GRADE DURING CONSTRUCTION (<1" VERTICAL CHANGE ANTICIPATED)			
Date Collected		9/20/2017 6:01:05 PM	Date Modified	11/20/2017 7:28:49 AM	