

Utility Conflict Report

| | | | | | | |
|-----------------------|-------------------------------------|---|--------------------|---|--------------------|--|
| OWNER | Utility | SAWS | Corridor | WW WHITE | SITE PHOTOS | |
| | Contact | NINA BITTLE | ID | 258 | | |
| GENERAL INFO | Utility | WATER | | | | |
| | Size and Material | STANDARD WATER METER, CAST IRON | | | | |
| | Utility Conflict Description | WATER METER WITHIN PROPOSED DRIVEWAY, INSIDE ACCESSIBLE ROUTE | | | | |
| | Longitudinal or Crossing | CROSSING | | | | |
| | Placement Relative to ROW | INSIDE | | | | |
| LOCATION | Sheet No. | 205 | | | | |
| | Station Origin | | | | | |
| | Start Station | 333+54.80 | End Station | | | |
| | Start Offset | 35.94 | End Offset | | | |
| | Latitude | 29.436824015 | Longitude | -98.405045372 | | |
| SUE | Level of Investigation Req'd | NONE | | | | |
| | Test Hole No | N/A | | | | |
| | Test Hole Depth | N/A | | | | |
| RESOLUTION | Recommended Action | MINIMIZE - PROTECT IN PLACE | | | | |
| | Estimated Resolution Date | | | | | |
| | Resolution Status | UTILITY COORDINATION IN PROGRESS | | | | |
| | Comment | ADJUST WATER METER LID TO PROPOSED GRADE DURING CONSTRUCTION (2-3" VERTICAL LOWERING ANTICIPATED) | | | | |
| Date Collected | | 11/29/2017 11:11:36 AM | | Date Modified 11/29/2017 11:56:32 AM | | |

