



Utility Conflict Report

OWNER	Utility	SAWS	Corridor	RIGSBY	SITE PHOTOS	
	Contact	NINA BITTLE	ID	267		
GENERAL INFO	Utility	WATER				
	Size and Material	STANDARD WATER METER, STEEL				
	Utility Conflict Description	WATER METER WITHIN PROPOSED DRIVEWAY, INSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing	CROSSING				
	Placement Relative to ROW	INSIDE				
LOCATION	Sheet No.	266				
	Station Origin					
	Start Station	530+82.01	End Station			
	Start Offset	18.54	End Offset			
	Latitude	29.398383065	Longitude	-98.395310515		
SUE	Level of Investigation Req'd	NONE				
	Test Hole No	N/A				
	Test Hole Depth	N/A				
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE				
	Estimated Resolution Date					
	Resolution Status	UTILITY CONFLICT RESOLVED				
	Comment	ADJUST WATER METER LID TO PROPOSED GRADE DURING CONSTRUCTION (2-3" VERTICAL RAISING ANTICIPATED)				
Date Collected		1/10/2018 1:24:35 PM		Date Modified	8/17/2018 2:20:40 PM	