



Utility Inventory Report

GENERAL INFO	<p>ID 175</p> <p>Corridor BS 123B</p> <p>Latitude +29.574623</p> <p>Longitude -97.964778</p> <p>Google Maps Hyperlink <a +29.574623,-97.964778"="" href="http://local.google.com/maps?q=">http://local.google.com/maps?q="+29.574623,-97.964778</p> <p>Field Notes 2 - 5.25'x1.5' grates</p>
UTILITY DETAILS	<p>Utility Grate</p> <p>Owner TXDOT</p> <p>Type Horizontal and Vertical</p>
SITE PHOTOS	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Photo 1</p>  </div> <div style="text-align: center;"> <p>Photo 2</p>  </div> <div style="text-align: center;"> <p>Photo 3</p> </div> </div>
<p>Date Collected 11/7/2017 2:07:11 PM Date Modified 12/11/2017 12:12:38</p>	