




## Sign Inventory Report

<b>GENERAL INFO</b>	<p><b>LOCID</b>            160</p> <p><b>Latitude</b>        +29.575566</p> <p><b>Longitude</b>      -97.96483</p> <p><b>Google Maps Hyperlink</b>    <a +29.575566,-97.96483"="" href="https://maps.google.com/maps?t=h&amp;q=">https://maps.google.com/maps?t=h&amp;q="+29.575566,-97.96483</a></p> <p><b>Field Notes</b></p>
<b>SIGN DETAILS</b>	<p><b>MUTCD_Code</b></p> <p><b>Sign_Condition</b>            Good</p> <p><b>Support_Condition</b>        Good</p> <p><b>Anchor_Condition</b>        Good</p> <p><b>Anchor_Type</b>              Triangular Slip Base</p> <p><b>Direction</b>                EB</p> <p><b>Retroreflectivity Check</b>   YES</p>
<b>SITE PHOTOS</b>	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>Photo 1</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 2</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 3</b></p>  </div> </div>
<p><b>Date Collected</b>    1/9/2018 11:03:14 AM                      <b>Date Modified</b>    1/23/2018 12:08:22 PM</p>	