

Utility Conflict Report

OWNER	Utility	CHARTER	Corridor	SW MILITARY	SITE PHOTOS
	Contact	FRANK CYPRIAN	ID	1092	
GENERAL INFO	Utility	COMMUNICATIONS			
	Size and Material	OVERHEAD TELECOMM LINES			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	LONGITUDINAL			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	166			
	Station	719+20.99			
	Offset	15.99			
	Latitude	+29.356537			
	Longitude	-98.50105			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date				
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Related to utility ID 4206			
Date Collected		Date Modified		12/18/2018 4:05:08 PM	

