

Utility Conflict Report

OWNER	Utility	CPS	Corridor	NOGALITOS	SITE PHOTOS		
	Contact	JAKE MARTINEZ	ID	3026			
GENERAL INFO	Utility	ELECTRIC					
	Size and Material	STANDARD POWER POLE, TIMBER					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.						
	Station	123+89.67					
	Offset	-23.8689					
	Latitude	+29.391397					
	Longitude	-98.51970					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date	8/13/2018					
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Pole ID: LW 59189; PL 467524. Pole to back of sidewalk = 4'-0" Guy wire vertical clearance = 7'-9" Guy wire to pole = 5'-0" Pole to fence = 6'-0" Adjacent to VIA bus stop no. 61897					
Date Collected		7/10/2018 10:01:54 AM		Date Modified		8/14/2018 4:38:26 PM	

