


Utility Conflict Report

OWNER	Utility	SAWS	Corridor	NOGALITOS	SITE PHOTOS 
	Contact	NINA BITTLE	ID	3039	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD FIRE HYDRANT			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station	133+06.85			
	Offset	38.9305			
	Latitude	+29.393360			
	Longitude	-98.51783			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/13/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Hydrant to face of curb = 4'-1" Sidewalk width = 7'-2"			
Date Collected		7/10/2018 2:36:28 PM		Date Modified	8/14/2018 4:38:26 PM

