

Utility Conflict Report

OWNER	Utility	tility PRIVATE		Corridor	NOGALITO)S	SITE PHOTOS	
	Contact	UNKNOWN		ID	3040			
0							259	
INFO	Utility		UNKNOWN				259	
	Size and Material		PETROLEUM TANK ACCESS					
GENERAL I	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE					
GEN	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		OUTSIDE ROW					
LOCATION	Sheet No.							
	Station 1	33+82.22						
	Offset 34.5298							
	Latitude +29.393360							
	Longitude -98.51770						259° BORE 259°	
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/13/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Underground petroleum tank access Fuel tank inlet to back of sidewalk = 8'-9 1/2"		'-9			
	Date Collected 7/10/2018 2:41:39 PM Date Modified 8/14/2018 4:38:26 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800