

Utility Conflict Report

OWNER	Utility	Utility CPS		Corridor	r NOGALITO	os .	SITE PHOTOS
\text{S}	Contact	JAKE MAR	TINEZ ID				STATE OF THE PARTY.
O							100
GENERAL INFO	Utility		ELECTRIC				
	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				H
LOCATION	Sheet No.						
	Station 1	135+05.69					
	Offset -	27.789					
	Latitude -	+29.393707					
	Longitude	-98.51748					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		8/13/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole ID: PL 395888; LW 51985. Pole marking: 2015 Pole to back of curb = 4'-3" Sidewalk width = 6'-5" Pole to edge of building = 2'-4"				
	Date Collected 7/11/2018 7:59:01 AM Date Modified 8/14/2018 4:38:26 PM						