

## **Utility Conflict Report**

OWNER	Utility	SAWS		Corridor	NOGALITOS	3	SITE PHOTOS	
×	Contact	NINA BITTI	LE	ID	3056			
0							10.575.5(9)	
INFO	Utility		WATER					
	Size and Material		STANDARD WATER METER, STEEL					
<b>GENERAL I</b>	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			UTE		
GEN	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
OCATION	Sheet No.						SIAS	
	Station 1	140+83.70						
	Offset -	31.8065						
	Latitude -	+29.395213						
٦	Longitude	-98.51640						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A				TELL BOOK STATE	
RESOLUTION	Recommended Action		NO CONFLICT					
	<b>Estimated Resolution Date</b>		8/13/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Top of meter to surface = 10"  Meter to back of sidewalk = 1'-9"  Sidewalk width = 5'-8"  Rubber lid thickness = 2"					
	<b>Date Collected</b> 7/11/2018 9:35:26 AM <b>Date Modified</b> 8/14/2018 4:38:26 PM							

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800