

Utility Conflict Report

OWNER	Utility	CPS	Corridor	NOGALITOS	SITE PHOTOS		
	Contact	JAKE MARTINEZ	ID	3071			
GENERAL INFO	Utility	ELECTRIC					
	Size and Material	STANDARD POWER POLE, TIMBER					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.	87					
	Station	138+49.45					
	Offset	22.4714					
	Latitude	+29.394310					
	Longitude	-98.51674					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date						
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Pole to back of sidewalk = 4'-0" Sidewalk width (at pole) = 6'-6" Sidewalk width (typical) = 4'-0" No pole ID					
Date Collected		7/11/2018 1:42:49 PM		Date Modified		8/15/2018 12:40:37 PM	

