




Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS	
	Contact	ANN PECHE	ID	3092		
GENERAL INFO	Utility	SANITARY SEWER				
	Size and Material	STANDARD MANHOLE, CAST IRON				
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing	CROSSING				
	Placement Relative to ROW	INSIDE ROW				
LOCATION	Sheet No.	123				
	Station	513+90.96				
	Offset	20.2407				
	Latitude	+29.358708				
	Longitude	-98.56531				
SUE	Level of Investigation Req'd	NONE				
	Test Hole No	N/A				
	Test Hole Depth	N/A				
RESOLUTION	Recommended Action	NO CONFLICT				
	Estimated Resolution Date	8/14/2018				
	Resolution Status	NO RESOLUTION WAS REQUIRED				
	Comment	Back of curb to sewer manhole = 6'-2" Edge of parking lot to sewer manhole = 8'-5" Bottom of cone to surface = 2'-8" Lid thickness = 1 1/2"				
	Date Collected	7/19/2018 10:22:45 AM	Date Modified	11/28/2018 6:59:12 AM		