

Utility Conflict Report

OWNER	Utility	UNKNOWN	Corridor	BANDERA	SITE PHOTOS		
	Contact	UNKNOWN	ID	3208			
GENERAL INFO	Utility	UNKNOWN					
	Size and Material	UNKNOWN					
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.						
	Station						
	Offset						
	Latitude	+29.499454					
	Longitude	-98.62446					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date	8/28/2018					
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Top of valve to surface = 1'-2 1/2" Edge of parking lot to valve = 12'-2" Text on lid reads "open left"					
Date Collected		8/17/2018 11:12:48 AM		Date Modified		11/28/2018 6:59:12 AM	

