

Utility Conflict Report

ER	Utility	CPS		Corridor	NOGALITOS	SITE PHOTOS	
OWNER	Contact	JAKE MARTINEZ		ID	4006	3 16	
GENERAL INFO	Utility		ELECTRIC			MARTI	
	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station 1	104+20.04					
	Offset 2	27.8541					
	Latitude +	+29.386979					
	Longitude -	-98.52329					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		8/13/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole ID: 44940 Back of curb to 3'-6" Pole to traffic: Pole to back of Pole to fence	o traffic sigr signal found of curb = 5'-4			
Date Collected 7/2/2018 9:20:54 AM Date Modified 8/14/2018 4:38:26 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800