

## **Utility Conflict Report**

OWNER	Utility	y SAWS		Corridor	NOGALITO	ns.	SITE PHOTOS		
	Contact	NINA BITTL	_	ID	4036	,0			
O	Contact	ontact NINA BITTE		-E 10					
GENERAL INFO	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUT			JTE			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.								
	Station 1	15+29.04							
	Offset -	34.5438							
	Latitude +	-29.389504							
	Longitude	-98.52138							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date		8/13/2018						
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Bottom of cone to surface = 8" Bottom of cone to lid lip = 7" Lid thickness = 1" Sidewalk width = 7'-2"						
Date Collected         7/3/2018 7:46 AM         Date Modified         8/14/2018 4:38:26 PM									

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800