

Utility Conflict Report

ER	Utility	SAWS		Corridor	NOGALITO	S	SITE PHOTOS	
OWNER	Contact	NINA BITTL	-E	ID	4059	, ,		
0						THE		
GENERAL INFO	Utility		WATER					
	Size and Material		STANDARD WATER METER, STEEL					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		NITE			
	Accessible Roule		ASSET IS OUTSIDE ACCESSIBLE ROUTE		JUIL			
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
\vdash	Sheet No.					A CONTRACTOR OF THE CONTRACTOR		
LOCATION		123+37.57						
		30.3767						
		+29.391205						
		-98.51983						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
NOIL	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/13/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Top of meter to surface = 8"					
<u>)L</u> [Meter to back of sidewalk = 1'-1"					
RESOLI						No. of the last of		
8								
							1	
	Date Collected 7/10/2018 9:09:05 AM Date Modified 8/14/2018 4:38:26 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800