

Utility Conflict Report

OWNER	Utility	CPS	Corridor	NOGALITOS	SITE PHOTOS
	Contact	JAKE MARTINEZ	ID	4070	
GENERAL INFO	Utility	ELECTRIC			
	Size and Material	STANDARD POWER POLE, TIMBER			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station	124+04.14			
	Offset	33.2532			
	Latitude	+29.391340			
	Longitude	-98.51948			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/13/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Pole marking: R14012 Pole to back of curb = 5'-7"			
Date Collected		7/10/2018 1:28:14 PM		Date Modified 8/14/2018 4:38:26 PM	

