

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	4082	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD WATER VALVE, CAST IRON			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	128			
	Station	528+15.25			
	Offset	24.9714			
	Latitude	+29.358290			
	Longitude	-98.56087			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/14/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Fence to valve = 4'-7" Unable to open lid			
Date Collected		7/23/2018 7:36:15 AM		Date Modified 11/28/2018 6:59:12 AM	

