

Utility Conflict Report

OWNER	Utility	UNKNOWN	Corridor	SW MILITARY	SITE PHOTOS	
	Contact	UNKNOWN	ID	4135		
GENERAL INFO	Utility	UNKNOWN				
	Size and Material	UNKNOWN				
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing	CROSSING				
	Placement Relative to ROW	INSIDE ROW				
LOCATION	Sheet No.	148				
	Station	636+54.55				
	Offset	21.7863				
	Latitude	+29.356455				
	Longitude	-98.52703				
SUE	Level of Investigation Req'd	NONE				
	Test Hole No	N/A				
	Test Hole Depth	N/A				
RESOLUTION	Recommended Action	NO CONFLICT				
	Estimated Resolution Date					
	Resolution Status	NO RESOLUTION WAS REQUIRED				
	Comment	Utility to back of sidewalk = 1" Utility box filled with rocks and water Utility not visible inside box No lid Square box had circular cast iron lid inside				
Date Collected		8/1/2018 8:41:36 AM		Date Modified 11/28/2018 6:59:12 AM		

