

Utility Conflict Report

IER	Utility	SAWS		Corridor	SW MILITA	ιRY	SITE PHOTOS
OWNER	Contact ANN PECH		ie id		4145		
GENERAL INFO	Utility		SANITARY SEWER				
	Size and Material		STANDARD MANHOLE, CAST IRON				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROU			JTE	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 155						
	Station 6	375+10.82					**************************************
	Offset 1	9.4633					
	Latitude +29.356624						
	Longitude	-98.51485					3
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				The second second
	Comment		Manhole to back of curb = 4'-11" Sidewalk width = 6'-0" Bottom of cone to surface = 1'-4 1/2" Lid thickness = 1 1/2"				
	Date Collected 8/1/2018 11:13:31 AM Date Modified 11/28/20						018 6:59:12 AM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800