

Utility Conflict Report

IER	Utility	SAWS		Corridor	SW MILITA	SITE PHOTOS
OWNER	Contact	ANN PECH	E	ID	4212	
GENERAL INFO	Utility		SANITARY SEWER			
	Size and Material		UNKNOWN			
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			DUTE
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No. 1	166				
	Station 7	20+05.73				
	Offset 2	20.6077				
	Latitude +	-29.356613				F
	Longitude	-98.50076				
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			
0,	Test Hole Depth		N/A			
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date					
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Back of sidewalk to utility box = 2'-1" Top of utility to surface = 3.5" Sidewalk width = 6'-8" Lid flange thickness = 1/2" Overall lid thickness = 1 5/8"			
Date Collected 8/7/2018 8:19:32 AM Date Modified 11/28/2018 6						11/28/2018 6:59:12 AM