

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	4607	
GENERAL INFO	Utility	SANITARY SEWER			
	Size and Material	SANITARY SEWER CLEANOUT			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	197			
	Station	880+57.94			
	Offset	-21.6054			
	Latitude	+29.356857			
	Longitude	-98.52253			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	Cleanout filled with water			
Date Collected		12/18/2018 8:41:50 AM		Date Modified 12/18/2018 8:42:07 AM	

