

Utility Conflict Report

OWNER	Utility	CPS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	JAKE MARTINEZ	ID	4618	
GENERAL INFO	Utility	ELECTRIC			
	Size and Material	1/2" CABLE, STEEL			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	172			
	Station	766+32.78			
	Offset	-17.59			
	Latitude	+29.358312			
	Longitude	-98.558296			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	ACCOMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment				
Date Collected		12/19/2018 2:25:53 PM	Date Modified		12/19/2018 2:31:52 PM

