

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	7014	
GENERAL INFO	Utility	SANITARY SEWER			
	Size and Material	STANDARD MANHOLE, CAST IRON			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	217			
	Station	1099+84.61			
	Offset	39.155			
	Latitude	+29.354220			
	Longitude	-98.42236			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/13/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Manhole in center of left turn lane Unable to open manhole			
Date Collected		8/2/2018 1:46:09 PM		Date Modified 11/28/2018 6:59:12 AM	

