

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	7061	
GENERAL INFO	Utility	SANITARY SEWER			
	Size and Material	SANITARY SEWER CLEANOUT			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	204			
	Station	910+45.00			
	Offset	-22.5529000000000001			
	Latitude	+29.356687			
	Longitude	-98.51306			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date				
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Top of cleanout to surface = 4" Cleanout adjacent to back of sidewalk Lid thickness = 1/2"			
Date Collected		8/3/2018 11:11:51 AM		Date Modified 11/28/2018 6:59:12 AM	

