

Utility Conflict Report

| IER | Utility | CPS | | Corridor | SW MILITARY | SITE PHOTOS | |
|--------------|----------------------------------|-----------|--|---|-------------|--|--|
| OWNER | Contact | JAKE MAR | TINEZ | ID | 7069 | | |
| GENERAL INFO | Utility | | ELECTRIC | | | | |
| | Size and Material | | STANDARD POWER POLE, TIMBER | | | | |
| | Accessible Route | | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | |
| | Longitudinal or Crossing | | CROSSING | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | | |
| LOCATION | Sheet No. | 155 | | | | | |
| | Station 9 | 901+93.75 | | | | | |
| | Offset -15.9 | | | | | | |
| | Latitude +29.356853 | | | | | | |
| | Longitude -98.51588 | | | | | | |
| SUE | Level of Investigation Req'd | | NONE | | | | |
| | Test Hole No | | N/A | | | | |
| | Test Hole Depth | | N/A | | | | |
| RESOLUTION | Recommended Action | | NO CONFLICT | | | e as Mar | |
| | Estimated Resolution Date | | 11/29/2018 | | | A STATE OF THE PARTY OF THE PAR | |
| | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | |
| | Comment | | Pole ID: 4546' Pole to back of Back of curb to Pole diameter No work propo | of sidewalk = 0 pole = 2'-7 = 12" | | INSURANCE ASEGURANZ 1923-570 | |

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

11/29/2018 1:30:24 PM

Date Modified

Date Collected

8/3/2018 11:38:21 AM