

## **Utility Conflict Report**

IER	Utility	SAWS		Corridor	SW MILITARY	SITE PHOTOS	
OWNER	Contact ANN PECH		E <b>ID</b>		7073	一人	
INFO	Utility		WATER			Tage -	
	Size and Material		STANDARD WATER METER, STEEL				
GENERAL	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
GEN	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	155					
	Station	901+35.92					
	Offset	-19.92					
	Latitude	+29.356802					
	Longitude	-98.51605					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE			INSUKANCE	
	Estimated Resolution Date					923-5700	
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY				
	Comment		Top of meter to surface = 6" Rubber lid thickness = 2" Meter adjacent to driveway joint				
	<b>Date Collected</b> 8/3/2018 11:51:52 AM <b>Date Modified</b> 11/28/2018 6:59:12 AM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800