

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	7127	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD WATER METER, STEEL			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	184			
	Station	782+89.72			
	Offset	-19.99			
	Latitude	+29.357783			
	Longitude	-98.55311			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	11/21/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Meter adjacent to driveway joint Top of meter to surface = 4" No lid			
Date Collected		8/6/2018 10:21:39 AM		Date Modified 11/28/2018 6:59:12 AM	

