

Utility Conflict Report

OWNER	Utility	AT&T	Corridor	SW MILITARY	SITE PHOTOS
	Contact	PHILIP AUSTIN	ID	1185	
GENERAL INFO	Utility	COMMUNICATIONS			
	Size and Material	UNKNOWN			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	LONGITUDINAL			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	216			
	Station	1149+20.00			
	Offset	20			
	Latitude	+29.352087			
	Longitude	-98.45690			
SUE	Level of Investigation Req'd	QLA			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	ACCOMMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	Underground communication lines shown on AT&T map ANMW-100 BU. CPPR. 72-STRAND BU. FBR. 1-PVC-4"			
Date Collected		Date Modified		11/21/2018 2:51:37 PM	

