




Utility Conflict Report

OWNER	Utility	CPS	Corridor	SW MILITARY	SITE PHOTOS   
	Contact	JAKE MARTINEZ	ID	7063	
GENERAL INFO	Utility	ELECTRIC			
	Size and Material	STANDARD POWER POLE, TIMBER			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	200			
	Station	907+71.08			
	Offset	-17.42			
	Latitude	+29.356786			
	Longitude	-98.51405			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	ACCOMMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	Pole ID: 501991 Back of curb to pole = 3'-1" Pole diameter = 10" Pole to back of sidewalk = 2'-0" Relocate pole to ROW with electric lines cantilevered toward the roadway			
Date Collected		8/3/2018 11:17:59 AM		Date Modified	11/21/2018 2:51:37 PM