

Utility Conflict Report

OWNER	Utility	CPS	Corridor	NOGALITOS	SITE PHOTOS
	Contact	JAKE MARTINEZ	ID	4007	
GENERAL INFO	Utility	ELECTRIC			
	Size and Material	STANDARD POWER POLE, TIMBER			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station	102+91.50			
	Offset	22.9795			
	Latitude	+29.386729			
	Longitude	-98.52355			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/13/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Pole to edge of sidewalk = 4'-6" Lines on pole: CPS and AT&T (telecommunications) CATV cable			
Date Collected		7/2/2018 9:30:36 AM		Date Modified 8/14/2018 4:38:26 PM	

