

Utility Conflict Report

OWNER	Utility	PRIVATE	Corridor	NOGALITOS	SITE PHOTOS	
	Contact	UNKNOWN	ID	4057		
GENERAL INFO	Utility	UNKNOWN				
	Size and Material	UNKNOWN				
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing	CROSSING				
	Placement Relative to ROW	INSIDE ROW				
LOCATION	Sheet No.					
	Station	123+09.70				
	Offset	27.369				
	Latitude	+29.391165				
	Longitude	-98.51965				
SUE	Level of Investigation Req'd	NONE				
	Test Hole No	N/A				
	Test Hole Depth	N/A				
RESOLUTION	Recommended Action	NO CONFLICT				
	Estimated Resolution Date	8/13/2018				
	Resolution Status	NO RESOLUTION WAS REQUIRED				
	Comment	LA Auto Upholstery sign pole Pole to back of sidewalk = 11" Sign vertical clearance = 8'-7"				
Date Collected		7/10/2018 8:55:56 AM		Date Modified 8/14/2018 4:38:26 PM		

