


## Data Collection Report

<b>GENERAL INFO</b>	<b>LOCID</b>	132	<b>Latitude</b>	+30.610345	
	<b>Project</b>	CR 366	<b>Longitude</b>	-97.462330	
			<b>Element</b>	Drainage	
	<b>Map Link</b>	<a href="https://maps.google.com/maps?t=h&amp;q=+30.610345,-97.462330">https://maps.google.com/maps?t=h&amp;q=+30.610345,-97.462330</a>			
	<b>Field Notes</b>	24" circular RCP			
<b>SITE PHOTOS</b>					
<b>Photo 1</b>					
<b>Date Collected</b>		6/20/2018 11:25:32 AM	<b>Date Modified</b>		
			6/20/2018 4:20 PM		

## Data Collection Report

SITE PHOTOS



Photo 2



Photo 3

**Date Collected** 6/20/2018 11:25:32 AM

**Date Modified** 6/20/2018 4:20 PM